## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. **DATED** 

: 6,848,948 B1

: February 1, 2005 INVENTOR(S) : Khemakhem et al. Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## Column 5,

Line 7, "Panel 10 is similar to panel" should read -- Panel 110 is similar to panel --. Line 27, "location to tic-off cables" should read -- location to tie-off cables --.

Signed and Sealed this

Sixteenth Day of August, 2005

JON W. DUDAS

Director of the United States Patent and Trademark Office